FCSC - Facility Audit Worksheet

Building: D Date: July, 9 2012

Overall Condition Rating:

Ву:

John Showalter

	Rating	Comments
	4	
elety Del 1	4	
Standard Foundations	4	
Slab on Grade	4	
•	4	
E SALUS AUGUNTES	4	
Floor Construction	4	
Roof Construction	4	
. Burto to the		
Exterior Walls	4	Painted summer 2010
Exterior Windows	4	
Exterior Doors	4	
5 (1/H)		
Roof Coverings		Painted summer 2010
Roof Openings		
Projections	4	
	4	
Advisor exturt that to		
Fixed & Movable Partitions	4	
Interior Doors	4	
Specialties	4	
imi tem Mai Bors		
Wall Finishes	4	Replace every 5 years. 2017 Budget \$3,000,00 per year
Floor finishes	4	Replace every 7 years 2019 Budget \$3,000.00 per year
Ceiling Finishes	4	
1	4	
$V_{\rm col} = 0.09 at ot p$	4	
Plumbing Fixtures	4	
Domestic Water Distribution	4	
Sanitary Waste	4	(See building A)
Rain Water Drainage	4	
Special Plumbing Systems	4	

FCSC - Facility Audit Worksheet

HVAC		
Energy Supply	4	Budget for annual supplies and repairs. (See Building A)
Heat Generating Systems	4	
Cooling Generating Systems	4	New Energy Saving heat pump HVAC system 2011 \$29,799.00
Distribution Systems	4	
Terminal & Package Units	4	
Controls & Instrumentation	4	
Special HVAC Equipment	NA	
Fire Protection	4	
Sprinkler Systems	NA	Consider installing sprinkler system 2013
Stand Pipe & Hose Systems	NA	
Fire Protection Specialties	4	
Special Fire Protection Systems	4	
Electrical		
Service & Distribution	4	
Lighting & Branch Wiring	4	
Communication & Security Systems	4	
Technology/Special Electrical Systems	4	
Conveying Systems		
Elevators	NA	
Stair & Chair Lifts	NA	
E. Equipment / Furnishings		
Furnishings		
Fixed Furnishings	NA	
Movable Furnishings	4	Budget for replacement furniture every year. (See Building A)
F. Special Construction	0	j j j j j j j j j j j j j j j j j j j
Special Construction		
Pool Construction	NA	
Pool Water Treatment System	NA	
Kitchen Equipment		
Preparation Equipment	NA	
Fire Suppression Hoods	NA	
Dishwashing Equipment	NA	
Freezers & Coolers	NA	
G. Building Sitework	4	
Site Improvements		
Roadways	4	Budget for annual seal coat and repairs. (See Building A)
Parking Lots	4	Budget for annual seal coat and repairs. (See Building A) Budget for annual seal coat and repairs. Sealed Aug.2010
Site Lighting	4	New energy saving parking lot lights 2011 \$24,650.00
		Total Chorgy Surving Parking for lights 2011 \$24,000.00

FCSC - Facility Audit Worksheet

Pedestrian Walks	4	
Rain Water Drainage	4	New gutters system Installed June 2010
Landscaping	4	Budget for annual supplies and equipment
ह जारमी/(देशन), एसमामा)		
Water Supply & Distribution Systems	4	
Sanitary Sewer Systems	4	(See Building A)
Storm Sewer Systems	4	
Fuel Supply	4	
Electrical Supply	4	
<u> </u>		